

From: [Miller, Garyg](#)
To: [Sanchez, Carlos](#)
Subject: FW: SJRWP Safety Requirements
Date: Thursday, March 31, 2016 6:52:00 AM

Carlos,

Picture of one of buoys washed up on cap; can barely see other buoys surrounding cap in distance (this is a vision test)

Gary Miller
Remedial Project Manager
EPA Region 6 – Superfund Division (6SF-RA)
214-665-8318
miller.garyg@epa.gov

From: Jacquelyn Young [mailto:jeyoung@texanstogether.org]
Sent: Wednesday, March 30, 2016 9:06 PM
To: Miller, Garyg <Miller.Garyg@epa.gov>
Subject: SJRWP Safety Requirements

Gary,

I received messages this evening from a Channelview resident complaining that several of the new buoys are floating away. One was mentioned to be near the center of the Pits. I just so happen to be out in the community this afternoon and snapped photos as we crossed over the River. I did not notice the buoy captured in my photos at the time, but I now see that I captured the buoy along the central berm.

Viewing the Site this afternoon I was happy to see the new safety equipment on Site. However, I am now disappointed to learn that the safety measures have not even been in place but a couple of weeks (at most) and are proving problematic. I'm not sure what went wrong or why buoys are floating away but this once again reinstates the lack of confidence we have in the PRPs conducting any work on Site. If something so simple goes wrong, how can we trust the integrity of their work with much larger tasks?

Also, the Coalition's monthly meeting is this Tuesday and I would like to be able to provide Site updates. I haven't received a response to my questions following the February meeting- could you maybe take a minute to tackle a couple of the questions related to the surveillance? Who will review the footage, how long will it be stored for, how often will it be reviewed, how will this be reported to the EPA?

I should be available most of tomorrow and Friday if you'd like to talk over the phone.

Thank you,
Jackie Young
281-414-3194



9768867